



CLASSE

Date: July 13, 2021

Model: Delta PRE

Software Update Number: V1.2.6.0

Software Update Notification

☒ RECOMMEND UPDATING ALL UNITS.

☐ UPDATE UNITS S/N: _____
PLEASE ADVISE CUSTOMERS AND UPDATE UNITS ONLY WHERE APPLICABLE.

☐ NEW FEATURES ADDED IN THIS SOFTWARE RELEASE ARE INTENDED TO IMPROVE OPERATION/PERFORMANCE. UPDATE IS OPTIONAL.

Dependencies and requirements for this software update (this info is accessible through pressing: MENU->STATUS):

N/A

V1.2.6.0 Release Notes: The following is list of changes since the last release of firmware.

+ : New Feature
● : Improvement
- : Bug Fix

- *Tone Control* and *Mono* buttons are now greyed out when using the Bypass output configuration.
- The *Bypass* output configuration is now greyed out when using digital sources.
- Tilt Control graph improved
- Added network connection status to the *Status* page
 - Fixed issue introduced in v1.2.5.0 with 0.25dB volume intervals not always matching with sound output.
 - Fixed Mono feature discrepancies after being disabled and enabling EQ.
 - Fixed EQ discrepancy when enabling tone control on analog sources.
 - Fixed various pages with using remote control navigation.
 - Fixed *Distance to Speakers* navigation when using remote control.
 - Fixed freezing issue within the *Distance to Speakers* page.
 - Fixed issue where some settings not appearing correctly after restoring defaults.
 - Fixed volume issue when switching between a pass thru and non-pass thru source.
 - Fixed version information texts after restoring defaults.

Sound United – Classe 380 rue McArthur Saint-Laurent, Québec Canada H4T1X8
Contact info Tel. : (877) 930-1127, Email : csupport@classeaudio.com

Release History

V1.2.5.0 (2021.01.24)

- Improved volume control method efficiency
- Fixed abrupt volume jump issue when combining custom *input offset* settings with balance control changes
- Fixed audio playback crash with USB-B when using Windows 10 in conjunction with Google Chrome

V1.2.1.0 (2021.01.12)

Fixed issue with the ability to rename inputs

V1.2.0.0 (2020.12.15)

- + Added support for sending the volume and mute status to the TV for HDMI and ARC sources
- + Shown configuration setting in use on home page
- + Added a feature for different auto-standby times (20 min, 1 hour, 2 hours, 4 hours or 8 hours)
- + Subwoofer indicator added on Home screen to identify if subwoofer(s) are enabled.
 - Improved signal path environment with analog sources. Unused components are powered down.
 - Fixed issue when plugging in USB drive for a user setting backup while screen is timed out.
 - Improved handling of SPDIF sources to avoid invalid non-PCM streams that may cause freezing of the UI
 - Modified handling of HDMI board to turn on System Audio and ARC on exit from standby, irrespective of the current source.
 - Subwoofer DAC is powered down when not required.
 - Modified the UI to force subwoofer operation to Mono when Mono mode is activated.
 - Modified Balance, Mono and Tone settings to be volatile (They will reset each time the unit comes out of standby)
 - GUI responsiveness has been improved
 - Improvements on the Phono Cartridge Loading page
 - Improvements on transition from an analog line source to phono source
 - Modified delay methods on *Distance to Speakers* and Subwoofer features
 - Updated Audio Delay GUI screens (distance rather than time).
 - Updated 'VERS' RS-232 command
 - Fixed the 'tick' sound heard when muting/unmuting
 - Custom names for configurations are now showing dynamically on the Configuration Selection page within input setup.

Release History (continued...)

- Updated HDMI firmware
 - Fixed issue with listening phono with headphones in XLR2
 - Volume dampening settings corrected and set to proper default value
 - Fixed issues connected with button timing
 - Fixed issue where unit is briefly irresponsive when changing inputs quickly
 - Fix SPDIF playback issue with certain CD players

V1.1.0.8 (2020.01.21)

- + Added functionality for different phono modes with F-keys
- + Added functionality for Headphone X-feed with F-keys
- Updated HDMI firmware
- Improved brownout / power failure performance
 - Fixed bug concerning abrupt cut of sound when navigating to source setup of the input currently used
 - Fixed several audio/video detection and glitches with HDMI
 - Fixed the issue of no audio when an HDMI source is selected with tone control enabled
 - Fixed trailing spaces in custom name entry in CAN-BUS
 - Fixed broken URL links / copyright text on web interface
 - Fixed issue with *Audio Delay* appearance on the configuration pages, if a sub output is not activated
 - Fixed appearance of response acknowledgements (ACK, NACK) with IP communications
 - Fixed the mute/unmute bug with analog inputs in bypass mode
 - Fixed the 'no audio' issue for digital sources after cycling through standby
 - Fixed CEC compatibility issues with mute/unmute
 - Fixed mute on startup with iOS device plugged in
 - Fixed issue with switching from USB-B to Airplay at high bit-rates

V1.0.0.0

Initial Release

Sound United – Classe 380 rue McArthur Saint-Laurent, Québec Canada H4T1X8
Contact info Tel. : (877) 930-1127, Email : csupport@classeaudio.com